




3/33


FIG. 4





(200















FIG. 11



OPERATIONS USED

		T
OPERATION	FUNCTION SUMMARY	SCRIPT SUMMARY
JobStart	START ISSUE OF JOB	SET JOB ATTRIBUTES BY SetJob AND TERMINATE SETUP BY JobEnd
SetJob	SET JOB ATTRIBUTES	SET JOB ATTRIBUTES NECESSARY FOR JOB AUTHENTICATION BY THIS OPERATION
Send	TRANSMIT PRINT DATA	
JobEnd	TERMINATE ISSUE OF JOB	
ExecuteJob	DESIGNATE EXECUTION OF JOB	DESIGNATE JOB EXECUTION TOGETHER WITH JOB ATTRIBUTES NECESSARY FOR JOB EXECUTION DESIGNATION AND JOB AUTHENTICATION BY THIS OPERATION

JobStart [TRANSMISSION PACKET]

Bit Byte	7	6	5	4	3	2	1	0
0~2		Pa	cket He	ader ID	& Vers	ion		
3	0	0	0	0	0	RqRep. (1)	Cont. (0)	Send (0)
4~5		Operation Code=id_val_operation_job_start						
6~7		Block Number=0x0001~0xFFFF						
8~9		Pa	rameter	Length=	=0x0009			
10~13		Us	er ID=	0x00000	000~0x	FFFFFF	F	
14~17	Password=0x00000000~0xFFFFFFF							
18~19		Status Code=0x0000						
20~23		Ob	ject Har	ndle (JO	B ID)			

Bit Byte	7	6	5	4	3	2	1	0
0~2		Pa	acket He	ader ID	& Vers	ion		
3	0	0	0	0	0	NoRep. (0)	Cont. (0/1)	Reply (1)
4~5		Op	peration	Code=i	d_val_op	eration_j	ob_start	
6~7		Bl	ock Num	nber=0x	0001~0	xFFFF		
8~9		Pa	rameter	Length=	=0x0004			
10~13		Us	er ID=	0x00000	000~0x	FFFFFF	F	
14~17		Password=0x00000000~0xFFFFFFF						
18~19		Status Code=0x0000~0xFFFF						
20~23		Ot	ject Ha	ndle (JO	B ID)			

SetJob [TRANSMISSION PACKET]

Bit Byte	7	6	5	4	3	2	1	0
0~2		Pa	acket He	ader ID	& Vers	ion		
3	0	0 0 0 0 1 1 1 1 1 1						Send (0)
4~5		O	peration	Code=i	d_val_op	eration_	Set_job	
6~7		Block Number=0x0001~0xFFFF						
8~9		Pa	rameter	Length=	=0x0003	~0xFFF	F	
10~13		Us	er ID=	0x00000	000~0x	FFFFFF	F	
14~17		Pa	ssword=	=0x0000	0000~0	xFFFFFF	FF	
18~19		Status Code=0x0000						
20~21		Attribute ID=0x0000~0xFFFF						
22~		Att	ribute D	ata=AN	Υ			

Bit Byte	7	6	5	4	3	2	1	0
0~2		Pa	icket He	ader ID	& Vers	ion		
3	0	0	0	0	0	NoRep. (0)	Cont. (0/1)	Reply (1)
4~5		O	eration	Code=i	d_val_or	eration_	Set_job	
6~7		Block Number=0x0001~0xFFFF						
8~9		Pa	rameter	Length=	=0x0003	~0xFFF	F	
10~13		Us	er ID=	0x00000	000~0x	FFFFFF	F	
14~17		Pa	ssword=	=0x0000	0000~0	xFFFFF	FF	
18~19		Status Code=0x0000~0xFFFF						
20~21		Attribute ID=0x0000~0xFFFF						
22~		At	ribute D	ata=AN	Υ			

Send [TRANSMISSION PACKET]

Bit Byte	7	6	5	4	3	2	1	0
0~2		Pa	icket He	ader ID	& Vers	ion		
3	0	0	0	0	0	RqRep. (0/1)	Cont. (0/1)	Send (0)
4~5		Op	eration	Code=i	d_val_op	eration_s	send	-
6~7		Block Number=0x0000~0xFFFF						
8~9		Parameter Length=0x0002~0xFFFF						
10~13		Us	er ID=	0x00000	000~0x	FFFFFF	F	
14~17		Pa	ssword=	=0x0000	0000~0	xFFFFFF	FF	
18~19		Status Code=0x0000						
20~21		Send Mode=0x00~0xFF						
22~		Se	nd Sour	ce=AN	/			

[ANSWER PACKET]

Bit Byte	7	6	5	4	3	2	1	0
0~2		Pa	cket He	ader ID	& Vers	ion		
3	0	0 0 0 0 NoRep. Cont. Reply (0) (1)						
4~5		Operation Code=id_val_operation_send						
6~7		Ble	ock Num	nber=0x	0000~0	xFFFF		
8~9		Pa	rameter	Length=	=0x0000)		
10~13		User ID=0x00000000~0xFFFFFFF						
14~17		Password=0x00000000~0xFFFFFFF						
18~19		Sta	atus Cod	de=0x00	000~0xF	FFF		

JobEnd [TRANSMISSION PACKET]

Bit Byte	7	6	5	4	3	2	1	0
0~2		Pa	cket He	ader ID	& Versi	ion		
3	0	0	0	0	0	RqRep. (0/1)	Cont. (0)	Send (0)
4~5		O	peration	Code=i	d_val_op	eration_j	ob_end	
6~7		Block Number=0x0001~0xFFFF						
8~9		Pa	rameter	Length=	0x0001			
10~13		Us	er ID=	0x00000	000~0xl	FFFFFF	F	
14~17		Password=0x00000000~0xFFFFFFF						
18~19		Status Code=0x0000						
20		Co	ntrol Fla	ag=0x00	01			

Bit Byte	7	6	5	4	3	2	1	0
0~2		Pa	icket He	ader ID	& Vers	ion		
3	0	0	0	0	0	NoRep. (0)	Cont. (0/1)	Reply (1)
4~5		Op	eration	Code=i	d_val_op	eration_j	ob_end	
6~7		Block Number=0x0001~0xFFFF						
8~9		Pa	rameter	Length=	=0x0005			
10~13		Us	er ID=	0x00000	000~0x	FFFFFF	F	
14~17		Password=0x00000000~0xFFFFFFF						
18~19		Status Code=0x0000~0xFFFF						
20		Control Flag=0x00~0x01						
21~24		Ot	ject Ha	ndle=0x	0000000	0~0xFF	FFFFFF	

ExecuteJob [TRANSMISSION PACKET]

Bit Byte	7	6	5	4	3	2	1	0
0~2		Pa	icket He	ader ID	& Vers	ion		
3	0	0	0	0	0	RqRep. (0/1)	Cont. (0)	Send (0)
4~5		Op	eration	Code=i	d_val_op	eration_e	execute_	job
6~7		Bk	ock Nun	nber=0x	0001~0	xFFFF		
8~9		Pa	rameter	Length=	=0x0004			
10~13		Us	er ID=	0x00000	000~0xl	FFFFFF	F	
14~17		Pa	ssword=	=0x0000	0000~0	xFFFFF	FF	
18~19		Sta	atus Coo	de=0x00	000			
20~23	Object Handle (JOB ID)							
24~25	Attribute ID=0x0000~0xFFFF							
26~		Att	ribute D	ata=AN	Υ			


Bit Byte	7	6	5	4	3	2	1	0	
0~2		Pa	cket He	ader ID	& Vers	ion			
3	0							Reply (1)	
4~5		O	peration	Code=i	d_val_op	eration_e	execute	job	
6~7		Block Number=0x0001~0xFFFF							
8~9		Pa	rameter	Length=	=0x0008				
10~13		Us	er ID=	0x00000	000~0x	FFFFFF	F		
14~17		Password=0x00000000~0xFFFFFFF							
18~19		Status Code=0x0000~0xFFFF							
20~23		Ob	ject Har	ndle (JO	B ID)		_		

JOB ATTRIBUTES USED


CLASSIFICATION	ATTRIBUTE	ATTRIBUTE IDENTIFIER
	JOB NAME	id_att_job_name
JOB ATTRIBUTES	TIME OF JOB SUBMISSION BY CLIENT	id_att_job_submission_time_on_client
	JOB ISSUER	id_att_job_originator
-	JOB RECIPIENT	id_att_job_owner
	JOB PASSWORD	id_att_job_passward

JOB DATA TRANSMISSION SEQUENCE FOR JOB ISSUE

111 PC 102 PRINTER



COMMAND DATA TRANSMISSION SEQUENCE FOR JOB EXECUTION DESIGNATION









FIG. 22


JOB ID	RECEPTION TIME	ISSUER	PASSWORD	RECIPIENT	PRINT DATA	~202a
00011	2000 / 02 / 10 10:45:15	×××	###	AAA (0), BBB (0), CCC (0)	00011.PRN	
-	1	1	1	1	1	
1	'	1	1	1		
!!!	!	!	1	1		
	!	!	!	!	!	
' '	'	'	'	'	1.	
1	1	1	1	1	-	
			1	1	1	
		-		1	1	
-			-	_ '	l	


110 ETHERNET














OPERATIONS USED

OPERATION	FUNCTION SUMMARY	SCRIPT SUMMARY		
JobStart	START ISSUE OF JOB	SET JOB ATTRIBUTES BY SetJob AND TERMINATE SETUP BY JobEnd		
SetJob	SET JOB ATTRIBUTES	SET JOB ATTRIBUTES NECESSARY FOR JOB AUTHENTICATION BY THIS OPERATION		
Send	TRANSMIT PRINT DATA			
JobEnd	TERMINATE ISSUE OF JOB			
Set	CORRECT JOB ATTRIBUTE	CORRECT JOB ATTRIBUTE IN ALREADY FORMED JOB DATA BY THIS OPERATION		
ExecuteJob	DESIGNATE EXECUTION OF JOB	DESIGNATE JOB EXECUTION TOGETHER WITH JOB ATTRIBUTES NECESSARY FOR JOB EXECUTION DESIGNATION AND JOB AUTHENTICATION BY THIS OPERATION		

F I G. 30

Set	
LUCISSIMSIANTI	PACKET

Bit Byte	7	6	5	4	3	2	1	0
0~2		Packet Header ID & Version						
3	0	0	0	0	0	RqRep. (0/1)	Cont. (0/1)	Send (0)
4~5		Operation Code=id_val_operation_set						
6~7	Block Number=0x0001~0xFFFF							
8~9	Parameter Length=0x0007~0xFFFF							
10~13	User ID=0x00000000~0xFFFFFFF							
14~17	Password=0x00000000~0xFFFFFFF							
18~19	Status Code=0x0000							
20~23	Object Handle (JOB ID)							
24~25	Attribute ID=0x0000~0xFFFF							
26~	Attribute Data=ANY							

Bit Byte	7	6	5	4	3	2	1	0
0~2		Pa	icket He	ader ID	& Vers	ion		
3	0	0	0	0	0	NoRep. (0)	Cont. (0/1)	Reply (1)
4~5	Operation Code=id_val_operation_set							
6~7	Block Number=0x0001~0xFFFF							
8~9	Parameter Length=0x0006~0xFFFF							
10~13	User ID=0x00000000~0xFFFFFFF							
14~17	Password=0x00000000~0xFFFFFFF							
18~19	Status Code=0x0000~0xFFFF							
20~23	Object Handle (JOB ID)							
24~25	Attribute ID=0x0000~0xFFFF							
26~	Attribute Data=ANY							

JOB ATTRIBUTES USED

CLASSIFICATION	ATTRIBUTE	ATTRIBUTE IDENTIFIER		
	JOB NAME	id_att_job_name		
	TIME OF JOB SUBMISSION BY CLIENT	id_att_job_submission_time_on_client		
	JOB ISSUER	id_att_job_originator		
JOB ATTRIBUTES	JOB RECIPIENT	id_att_job_owner		
	JOB VALIDITY PERIOD	id_att_job_discard_time		
	THE NUMBER OF EXECUTABLE TIMES OF JOB	id_att_job_available_count		
	JOB PASSWORD	id_att_job_passward		

COMMAND DATA TRANSMISSION SEQUENCE FOR JOB ATTRIBUTE CORRECTION

103 PC 102 PRINTER

TRANSMIT Set

RETURN Set

CORRECT THE NUMBER OF EXECUTABLE TIMES OR JOB RECIPIENT AS JOB ATTRIBUTE

